


`



(

Table 1: FIGURE 49

	Billet manufacturing process					Aspect ratio	Crack
	Spherodizing annealing prio to drawing			Spherodizing	Shot bonderizing	of carbide	percentage % N=100
Material	None	None	0	0	0	506	35%
Material 2	None	(20%) O	0	0	0	347	5%
Material (0	(20%) O	0	0	0	300	0%

Aspect ratio (%) = $b/a \times 100$

